

LED – Guideline for connection

1. Board with LED strips:



2. Assemble the remote control signal receiver onto board, using the given screws.



3. Connect the signal receiver to the strip (make sure that the arrows are facing each other).



4. Plug in the round end of the connecting cord to the signal receiver.



5. Plug in the USB end of the connecting cord to the battery.



6. Plug in the end of the power cord to the battery.




7. Turn on the battery. (Please keep the battery on while recharging. The red light should be on.)




8. Plug into the power supply to recharge the battery.




9. Keep on recharging till the power supply lamp show green color and battery is full. (It will take 6 – 7 hours)



10. While charging the battery, aim the top of the remote controller at the signal receiver, press "on".



11. If the LED lights do not work, turn the signal receiver end to the other side, and plug in again.



12. (The battery can work for 2-5 hours without connecting to power supply, depending on the light brightness.)

